

# DIVISION OF MINES BOARD OF COAL MINING EXAMINERS CERTIFICATION REQUIREMENTS http://www.dmme.virginia.gov/divisionmines.shtml

## SURFACE ELECTRICAL REPAIRMAN

Article 3 of the <u>Coal Mine Safety Laws of Virginia</u> establishes requirements for certification of coal mine workers. The certification requirements are included in §45.1-161.24 through §45.1-161.41 in which the Board of Coal Mining Examiners is established for the purpose of administering the certification program. The Board has promulgated certification regulations 4 VAC 25-20, which set the minimum standards and procedures required for Virginia coal miner examinations and certifications.

#### CERTIFICATION CLASSIFICATION: \*Surface Electrical Repairman

This certification authorizes the holder to:

- Perform electrical work and inspections at surface locations of underground coal mines, preparation plants, and at surface (strip) coal mines (any surface location)
- Make examinations on electrical equipment
- Conduct and record results of electrical examinations

#### **APPLICATION/EXPERIENCE REQUIREMENTS:**

- Application (BCME-1) and \$40.00 fee 5 working days prior to examination
- One year of electrical experience in surface coal mining under the direction of a certified surface electrical repairman or appropriately related work experience approved by the Chief of the Division of Mines
- Six months credit will be granted for electrical training from a college, technical school, or vocational school
- Hold a General Miner Certification
- Current first aid training (MSHA 5000-23 Annual Retraining or New Miner Inexperienced Training acceptable)

### **EXAMINATION REQUIREMENTS:** A score of 80% on each element of the examination

ELEMENTS OF EXAM	NUMBER OF QUESTIONS
<ul> <li>Alternating Current (AC)</li> </ul>	20
<ul><li>Direct Current (DC)</li></ul>	20
<ul> <li>Circuits &amp; Equipment/drawings (CE)</li> </ul>	25
<ul><li>Cable Splicing (CS)</li></ul>	20
<ul><li>High Voltage (HV)</li></ul>	20
<ul> <li>Legal Requirements (LR)</li> </ul>	20
<ul><li>Permissibility (PR)</li></ul>	20
• First Aid (FA)	20
<ul> <li>Gas Detection - practical demonstration</li> </ul>	

- Gas Detection practical demonstration
- Records Practical Stations (5)
  - 1. Control Circuit Troubleshooting Electrical Schematic Reading (ER)
  - 2. Electrical Examinations Record Keeping (RK) (Surface)
  - 3. Cable Troubleshooting (CT)
  - 4. Circuit Breaker Troubleshooting (CB)
  - 5. Permissibility (PD)

- continued on back -

#### RECOMMENDED REFERENCE/STUDY MATERIALS:

- Electrical Study Guide/Student Training Guide
- Coal Mine Safety Laws of Virginia
- BCME Requirements
- First Aid for Miners Study Guide
- Title 30 CFR Parts 18, 75, 77
- Mine Gases Packet

The above mentioned study materials are available at the Department of Mines, Minerals and Energy's Big Stone Gap Office, Customer Assistance Center (276) 523-8233 and Keen Mountain Field Office (276) 498-4533.

\*8 hours annual continuing education required to update certification.

Revised 06/25/07